


T.One



Pre-press the garment 3 to 5 seconds and position the T.One transfer face-down on the hot surface.




Note: Wait a few seconds before stripping off the base paper. Strip liner right on the heat press in one slow steady motion in a very shallow angle!

If desired place a sheet of T.Foil over the image, cover with release paper and press for 3 to 5 Sec. Let cool down and remove the T.Foil liner.

Important for washing durability in any case: Cover the image with T.Seal and press again for 10(A4) to 15(A3) seconds for the final seal !

Note: First wash after minimum 48 hours only!

PRINT




T.One




MIRROR

PRESS



140°C
285°F




3-5 SEC



80 PSI
HIGH

STRIP



HOT